Tom E. Tynan Vice President Vogtle -Units 1 & 2 Southern Nuclear Operating Company, Inc. 7821 River Road Waynesboro, GA 30830

Tel 706 826 3151 Fax 205 980 3321



May 30, 2014

Docket No: 50-425

NL-14-0809

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555-0001

> Vogtle Electric Generating Plant – Unit 2 Licensee Event Report 2014-001-00 Automatic Reactor Trip Due To Low Steam Generator Level

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(iv)(A), Southern Nuclear Operating Company (SNC) is submitting the enclosed Licensee Event Report, 2-2014-001. This letter contains no NRC commitments. If you have any questions, please contact Kevin Walden at (706) 848-4290.

Respectfully submitted,

Tom E. Tynan

Site Vice President - Vogtle

Tom T. Tyran

TET/KCW

Enclosure: Unit 2 Licensee Event Report 2014-001-00

cc: Southern Nuclear Operating Company

Mr. S. E. Kuczynski, Chairman, President & CEO

Mr. D. G. Bost, Executive Vice President & Chief Nuclear Officer

Mr. T. E. Tynan, Vice President - Vogtle 1 & 2

Mr. B. L. Ivey, Vice President - Regulatory Affairs

Mr. D. R. Madison, Vice President - Fleet Operations

Mr. B. J. Adams, Vice President - Engineering

Mr. S. C. Waldrup, Regulatory Affairs Manager - Vogtle

Mrs. M. A. Cline, Operating Experience Coordinator - Vogtle

RType: CVC7000

U. S. Nuclear Regulatory Commission

Mr. V. M. McCree, Regional Administrator

Mr. R. E. Martin, NRR Senior Project Manager -Vogtle

Mr. L. M. Cain, Senior Resident Inspector - Vogtle

## Vogtle Electric Generating Plant – Unit 2 Licensee Event Report 2014-001-00 Automatic Reactor Trip do to Steam Generator Low Level

### Enclosure

Unit 2 Licensee Event Report 2014-001-00

## NRC FORM 366

U.S. NUCLEAR REGULATORY COMMISSION APPROVED BY OMB: NO. 3150-0104

2. DOCKET NUMBER

05000425

EXPIRES: 01/31/2017

1 OF 3

02-2014)

1. FACILITY NAME

Voqtle Electric Generating Plant – Unit 2

## LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

3. PAGE

				,							!		·	•	
4. TITLE Auto		Reactor	Trip Du	ue To Low	Stear	n Gener	ator I ev	el					-,,-	,	
, 10.10					0.00										. —
5. E	VENT D	ATE	6. LER NUMBER			7. R	7. REPORT DATE			8. OTHER FACILITIES INVOLVED					
монтн	DAY	YEAR	YEAR	SEQUENTIAI NUMBER	REV NO.	MONTH	DAY	YEAR	N/	FACILITY NAME  OCKET NUMBER  N/A					
04	08	2014	2014	- 001	- 00	05	30	2014	PA N/	A DOCKET NUMBER					IUMBER
9. OPERATING MODE 11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)															
			20.2201(b)				20.2203(a)(3)(i)			50.73(a)(2)(i)( <b>C</b> )			50.73(a)(2)(vii)		
			20.2201(d)				20.2203(a)(3)(ii)			50.73(a)(2)(ii)(A)			50.73(a)(2)(viii)(A)		
1			20.2203(a)(1)				20.2203(a)(4)			50.73(a)(2)(ii)(B)			50.73(a)(2)(viii)(B)		
			20.2203(a)(2)(i)			;	50.36(c)(1)(i)(A)			50.73(a)(2)(iii)			50.73(a)(2)(ix)(A)		
10. POWER LEVEL		20.2203(a)(2)(ii)				50.36(c)(1)(ii)(A)			50.73(a)(2)(iv)(A)			50.73(a)(2)(x)			
			20.2203(a)(2)(iii)			Ü	50.36(c)(2)			50.73(a)(2)(v)(A)			73.71(a)(4)		
	100	ı	20.2203(a)(2)(iv)				50.46(a)(3)(ii)			50.73(a)(2)(v)(B)			73.71(a)(5)		
	100		20.2203(a)(2)(v)			Ü	50.73(a)(2)(i)(A)			50.73(a)(2)(v)(C)			OTHER		
		20.2203(a)(2)(vi)				50.73(a)(2)(i)(B)			50.73(a)(2)(v)(D)			Specify in Abstract below or in NRC Form 366A			
					1	2. LICEN	SEE CON	TACT FO	R TI	HIS LER					
	CONTACT Electri	c Gene	rating F	Plant, Kev	in Wak	den, Lice	ensing E	ngineer			i i		NE NUMBER 26-4290	•	Area Code)
			13. CO	APLETE ON	E LINE	FOR EAC	H COMP	DNENT F	AILU	RE DESCRIBI	D IN THIS	REPO	RT		
CAUS			сом	COMPONENT MANU- FACTURER			REPORTABLE CAUS		SE	SYSTEM COMPONENT		IENT	MANU- FACTURER		EPORTABLE TO EPIX
В		SJ		JB	Ovatio	n	Υ								
14. SUPPLEMENTAL REPORT EXPECTED							_		(PECTED		MONTH	DAY	YEAR		
☐ YE	ES (If ye:	s, comple	te 15. EX	(PECTED S	JBMISS	ION DATE	E) 🛛 I	NO		) su	BMISSION Date	l			
ABSTRAC	CT (Limit	to 1400 sp	aces, i.e.,	approximately	•		oewritten lin	•				_			

On April 8, 2014 at approximately 04:30 Eastern Standard Time, Vogtle Unit 2 was operating at Mode 1 at 100 percent power when Unit 2 received a Steam Generator 3 narrow range low-low level automatic Reactor Protection System actuation as a result of the Loop 3 Main Feedwater Regulating Valve failing closed. The RPS actuation resulted in a trip of the turbine-generator. All rods fully inserted into the core, the Main Feedwater Isolation system and the Auxiliary Feedwater system automatically actuated as expected. The plant was stabilized in Mode 3 and the decay heat was discharged to the condenser. The cause of the event was a failure of the Steam Generator 3 Main Feed Regulator Valve control system.

The safety significance of the event is very low. Unit 1 was not affected and there were no adverse effects on the health and safety of the public.

(02-2014)



Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported tessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET	6	. LER NUMBER			3. PAGE	E
Vestle Fleetric Concreting Plant   Unit 2	05000425	YEAR	SEQUENTIAL NUMBER	REV NO.		OF	2
Vogtle Electric Generating Plant – Unit 2		2014	- 001 -	00	2		3

#### NARRATIVE

#### A. REQUIREMENT FOR REPORT

This report is required per 10CFR 50.73(a)(2)(iv)(A) due to an unplanned automatic actuation of the Reactor Protection System (RPS) and automatic actuation of the Auxiliary Feedwater System (AFW) and Feedwater Isolation (FWI) Engineered Safety Features Actuation Systems (ESFAS).

#### B. UNIT STATUS AT TIME OF EVENT

Mode 1, 100 percent power

#### C. DESCRIPTION OF EVENT

While operating at 100 percent power, Unit 2 experienced a low-low level alarm in Steam Generator 3. This resulted in an automatic RPS actuation due to low-low level in Steam Generator 3. AFW actuated and Main Feedwater isolated following the RPS actuation, as expected. All rods inserted and the plant was stabilized in Mode 3. Decay Heat was discharged to the condenser and no complications were experienced during the trip as all systems responded as designed.

The source of the water intrusion into the primary MFRV positioner was the result of a small leak (3 drops per minute) approximately eighteen feet above the positioner conduit. The collection area of the water was not immediately identified and as a result of less than adequate installation of the flex conduit, water accumulated inside the positioner housing. Over time, the accumulation of water inside the positioner housing reached a level resulting in an electrical short circuit of the primary MFRV positioner. This resulted in erroneous feedback from the primary positioner to the digital control system. This condition existed until the Loop 3 MFRV suddenly closed.

#### D. CAUSE OF EVENT

The cause of the event was failure to maintain installation standards of non-safety related conduit for the MFRV digital control system resulting in primary positioner water intrusion.

#### E. SAFETY ASSESSMENT

When the reactor tripped, all rods fully inserted. As a result of the trip, a FWI occurred and the AFW system actuated as designed. The unit was stabilized in Mode 3 at normal temperature and pressure. Because the plant responded as designed and there were no complications with plant shutdown, there was no adverse effect on plant safety or the health and safety of the public.

## NRC FORM 366A

(02-2014)

# LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

11 9	NUCL	FAD	PEGIII	ATORY	COMMISSION
U.S.	NUCL	EAR.	KEGUL	AIURI	COMMISSION

1. FACILITY NAME	2. DOCKET		3. PAGE				
Vogtle Electric Generating Plant – Unit 2	05000425	YEAR	SEQUENTIAL NUMBER	REV NO.	3	OF	2
		2014	- 001 -	00			3

#### **NARRATIVE**

#### F. CORRECTIVE ACTION

Immediate interim action to inspect and seal the flex conduit to the remaining MFRV positioners was completed for both Unit 1 and Unit 2. Quality Control inspections will be required for conduit installation on critical components to ensure design and installation standards are maintained.

#### G. ADDITIONAL INFORMATION

1) Failed Components:

MFRV Primary Positioner

2) Previous Similar Events:

IER 13-14-12 "Water Intrusion into Relay Box Causes Main Feedwater Isolation Valve Closure and Manual Scram"

3) Energy Industry Identification System Code:

[JB] -Feedwater/Steam Generator Water Level Control System

[JC] -Reactor Protection System

[BA] -Auxiliary Feedwater System